

FIELD INSPECTION REPORT

Date of Inspection :	5.12.2022	District:	Dindigul
Division :	Bamapur	Length (km):	1.00
Name of the Road:	Shanpur to LO27		
Scheme/Programme:	MAINTENANCE	SPTA	
Package No.:	GTSNY	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	1

ASPH
5/12/2022

NAME: M. G. S. Arun

DESIGNATION: S. E. Alingar

5/12/2022
A. E. Alingar

(Signature)