

FIELD INSPECTION REPORT

Date of Inspection : 15.12.2020		District : GAYA	
Division : Neemchak Bathani		Length (Km.) : 1.111 km	
Scheme/Programme:		MAINTENANCE	
Package No. : BR-65-R-565		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History		
a)	Status of ATR's & any others.		
Overall Rating :			
Satisfactory (S)			-
Satisfactory but requires improvement (SRI)			SRI
Unsatisfactory (U)			-

By 15.12.2020
J.E