

FIELD INSPECTION REPORT

Date of Inspection : 16/12/20	District: E. Champaran
Division : Raxaul.	Length (km): 5.80km
Name of the Road: NH-28A to Meenatala (Port of length of 5.38km of NH-28A to Madhubani)	
Scheme Programme: MAINTENANCE MR-3054	
Package No.:	Road Id No.: 31708508033
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NOTE:- This road is badly damaged in FDR-2017, 18 & 2019
 So Fresh Estt is submitted in H.Q under
 MR-3054 (New Maintenance Policy) for A.A

(Signature) 16/12/20

NAME: Chaitant Singh
 DESIGNATION: Junior Engineer.