

FIELD INSPECTION REPORT

Date of Inspection : 15/12/2020	District: Samastipur
Division : Dalsingh sarani	Length (km): 0.850 km
Name of the Road: NH 103 Banbira chottha maddi a vidyalayaria west shori	
Scheme/Programme: MAINTENANCE old MR	Promod Roy up Pramuks
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U //
c)	Riding Quality	S/U //
d)	Road Camber	S/U //
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No //
f)	Contraction Joints provided or not (CC Pavement)	Yes/No //
g)	Compaction of flank/slope & raincuts if any	Yes/No //
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U //
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U //
c)	Condition of railings/slab/approach for Bridges	S/SRI/U //
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No //
4.	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	N/A

Note - out of 5 years Maintainance

NAME: Manojay Prasad

DESIGNATION: J.E.


(Signature)