FIELD INSPECTION REPORT

Date o	f Inspection: 03.	2 2020 District: Katihar.	
	on : Katihar	Length (KM) + 9.2-14	
Name of Road:		Dumar to ckhohar (Bhangaha)	
Scheme/ Programme:		MAINTENANCE	
acka	ge NoM/R-NID	20 Kerifan /09 Road ID No. 21105508073	
Status of the Project:		Onging/Completed/Under Maintenance	
Vork	is a case of:	New Connectivity/ Up Gradation/ Maintenance	
SI.No		Parameters to be Checked	Remarks
. 1	Pavement		
a)	Road Junction Cond	lition	S/U NA
b)	Condition of Surfac	ing	S/U HA
c)	Riding Quality		S/U NA
d)	Road Camber		S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No NA
f)	Contraction Joints p	rovided or not (CC Pavement)	Yes/Nonp
g)	Compaction of flank/slpoe & raincuts if any		✓Yes/No Par
2	Cross Drainage		
a)	Condition of headw	alls inn Humepipe culverts including its painting	S/SRI/UNA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/UNA
c)	Condition of railing	s/slabs//approach for Bridges	S/SRI/UNA
3	Road Furniture		9 -
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		
4	Compliance Histor	y	
a)	Status of ATR & an	y others	NO
overall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	- 4
		ar (83.9.9	290
•	vijay kum	ar (Signature)	

Name: Vijay Kumar Degisnation - A. E. Katikar

R.W.D. Works Div., Katihar

Scanned by CamScanner