FIELD INSPECTION REPORT

Date of Inspection:	16-12-2020	District: PURNEA	
Division:	BAISI	Length (km): 5.0 Km	
Name of the Road:	Anwar chowk se shaura hel.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U/
b)	Condition of Surfacing	\$/U
c)	Riding Quality	\$/U
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y¢Š/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	1000
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SET
Unsatisfactory (U)	

(Signature)

NAME: Kamlesh chaudhazy DESIGNATION: chief Engineer