FIELD INSPECTION REPORT

Date of Inspection: 16-12-2020 District: PURNEA					
Division: BAISI			Length (km): 3.20 Km		
Name of the Road: Repair of Load from Bhausa Bridgeto Jawas.					
Scheme/Programme: MAINTENANCE					
Package No.: Road Id No.:					
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
SI. No.		Parameters to	be checked	Remarks 🗉	
de	Pavement				
a)	Road Junction condition			S/U/	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			√S/U	
e)	Whether free aggregates in c	Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b) •	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRA/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
31	Road Furnitur				
a)	Whether sign stones/Pavemen	Yes/No			
4.	Compliance Hi	story		in the second se	

Overall Rating

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

Kamlesh chaudhoug

Status of ATR's & any others

DESIGNATION.

ief Engineer