FIELD INSPECTION REPORT

Date of I	nspection:	15/12/2020	District: Supoul		
Division	: Su	paul	Length (km): 7.95		
Name of	the Road:	Lisauni from	nd to Abhuwar fus r	oad	
Scheme/	Programme:	MAINTENANCE			
Package		,	Road Id No.: 2.100490	8065	
and the state of t	f the Project:		/Under Maintenance-		
Work is	a case of:	New Connectivity/U	p gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junctio	on condition	\$/U		
b)	Condition of	Surfacing	S/U blo	yt at very	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Xes/No	
f)	Contraction Joints provided or not (CC Pavement)			¥es/Ne	
g)	Compaction	of flank/slope & raincu		est sain cut	
2.	Cross Drainage				
a)	Condition of	head walls in Hume pig	pe culverts including its painting	S/SRI/U	
b)	Condition of	Abutment & Wing wal	ls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N	·A-
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
134.	Compliance History				
a)	Status of ATR's & any others			Not recuir	ed
Oue-11	Datina		•		1
Overall	Raung	Satisfactory (S)	T		
		Satisfactory but	requires Improvement (CDI)		1

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: SANJEOU FUMAL

DESIGNATION: EXECUTIVE ENGINEER

CC 3 off, fro, fatha