FIELD INSPECTION REPORT

Date of Inspection: 16-12-2020			District: NALANDA		
Division: Harnend			Length (km): 2. 7 km.		
Name of	the Road: N+	130 to Lachhule	igha Via Uhmemper		
Scheme/	Programme: '	MAINTENANCE	MR-3054		
Package			Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
Work is	a case of:				
Sl. No.		Parameters to be checked		Remarks	
1.	Pavement				
n)	Road Junction condition			S/US	
b)	Condition of Surfacing			S/U V	
c)	Riding Quality			S/U'U	
d)	Road Camber			S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No N/	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No/e	
g)	Compaction of flank/slope & raincuts if any			Yes/No/	
2,,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/USA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges S/SI			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No _{Nũ}	
74.5°	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	- 10 TV
Unsatisfactory (U)	U

(Signature)

NAME: Rama Basin Kimas Singh DESIGNATION: Executive Enfinely.

Scanned with CamScanner