

FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020 District: Bettiah
 Division : - RWD. Muzkara-Bettiah Length (km): - 3.
 Name of the Road: - 1055-1028 to Naw Katula
 Scheme/Programme: MAINTENANCE
 Package No.: 006 Road Id No.: 3180882143
 Status of the Project: Ongoing Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance - New maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones. Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N.A

Work has not started

Notice Issued -

(Signature)

16-12-20

NAME: - Rakesh Paswan

DESIGNATION: Executive Engineer.