

FIELD INSPECTION REPORT

15/12/20
AE

Date of Inspection :	<i>15.12.20</i>	District:	<i>Aurangabad</i>
Division :	<i>Aurangabad</i>	Length (km):	<i>6.50 Km</i>
Name of the Road:	<i>Eoka Budhna to Barianum Road</i>		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is in case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<i>✓ S/U</i>
b)	Condition of Surfacing	<i>S/U ✓</i>
c)	Riding Quality	<i>S/U ✓</i>
d)	Road Camber	<i>S/U ✓</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<i>Yes/No ✓</i>
f)	Contraction Joints provided or not (CC Pavement)	<i>Yes/No ✓</i>
g)	Compaction of flank/slope & raincuts if any	<i>✓ Yes/No</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<i>S/SRI/U ✓</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<i>S/SRI/U ✓</i>
c)	Condition of railings/slab/approach for Bridges	<i>S/SRI/U NA</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>✓ Yes/No</i>
4.	Compliance History	
a)	Status of ATR's & any others	<i>—</i>

Overall Rating :

Satisfactory (S)	<i>—</i>
Satisfactory but requires Improvement (SRI)	<i>—</i>
Unsatisfactory (U)	<i>U</i>

NAME:

(Signature)

16/12/20
E.E
R Lab
Gulzarbag
Path