

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District: NALANDA
Division : Harnant		Length (km): 4.4 Km
Name of the Road: M-30A to Badihi Mose via Kaila		
Scheme/Programme: MAINTENANCE		MR-3054
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <input checked="" type="checkbox"/>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <input checked="" type="checkbox"/>
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/> No raincut
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/USRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <input checked="" type="checkbox"/>
4.	Compliance History	
a)	Status of ATR's & any others	<input checked="" type="checkbox"/>

Overall Rating :

Satisfactory (S)	<input checked="" type="checkbox"/>
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	<input type="checkbox"/>

Rana Basu Kumar Singh
16.12.2020
(Signature)

NAME: Rana Basu Kumar Singh
DESIGNATION: Executive Engineer.