## FIELD INSPECTION REPORT

Date of I	nspection: 16.12.2020 District:	jwan.	
Division: Mahasgant, Length (km): 2.330			
Name of	V O CHUBIT	akhondolinjous.	
Scheme/	Programme: MAINTENANCE		
Package No.: Road Id No.:			
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is	a case of: New Connectivity/Up gradation/ Main	1	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible craaggregates in case of CC Pavement.	icks, exposed Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No 1	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts includi	ng its painting S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC cu	alverts S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRÍ/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Boards/stones/Pavement road markings are provided and main	/km & 200m ntained Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U:

Rakesh Ranjan Pandry.

Coxembre Engineer.

NAME: % CE-1.

(Signature)

DESIGNATION: