

FIELD INSPECTION REPORT

Date of Inspection :	16/12/2020	District:	East Champaran
Division :	Motihari	Length (km):	3.0
Name of the Road:	Repair of PWD Madhubani Ghat. Agri. Vard College to Basuan		
Scheme/Programme:	MAINTENANCE		
Package No.:	—	Road Id No.:	31708208107
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement?	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	N-A	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

(Signature) 16/12/20

NAME: Bondu Rajak

DESIGNATION: Executive Engineer

R.W.D.
Regional Laboratory Darbhanga