

FIELD INSPECTION REPORT

Date of Inspection : 16/12/20		District: East Champaran
Division : Motihari		Length (km): 4.0
Name of the Road: Turkauliya Samera station appd to Samera Bazar		
Scheme/Programme: MAINTENANCE		VIA Mahawa Bazar Bazar
Package No.: —		Road Id No.: 31708208116
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		3054
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

deia
(Signature) 16/12/20

NAME: Bindu Rajan

DESIGNATION: Executive Engineer
R.W.D
Regional Laboratory Darbhanga