

FIELD INSPECTION REPORT

Date of Inspection : 15.12.2020		District: DARBHANGA
Division : DARBHANGA-1		Length (km): 3.2 km
Name of the Road: KANGWA GUMTI NH-57 To RANIPUR HANDELA CAUTIONARY TOLLS		
Scheme/Programme: MAINTENANCE		
Package No.: MA (8054)/ET/2016-17	Road Id No.: 31909208157	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NO
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

In small stretches road length- damaged in flood which are reported under PDR.

[Signature]
(Signature)

NAME: K. R. RANJAN

DESIGNATION: BA