

FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District: Samashpur
Division : Samashpur		Length (km): 3.00km (East to West)
Name of the Road: PWD Malpura Chowk to Dadpur Achey via Bhairavdehra Imli Chowk Simha Khand Panchayat		
Scheme/Programme: MAINTENANCE		old mixt
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		✓
Work is a case of: New Connectivity/Up gradation/ Maintenance		✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	+
Unsatisfactory (U)	U

Samiksha
(Signature) 16/12/20

NAME: SAMIR KUMAR

DESIGNATION: F.E