

FIELD INSPECTION REPORT

Date of Inspection : 16/12/20	District: Samaspur
Division : Samaspur	Length (km): 2.45
Name of the Road: SH Toh to Chak Abdulgani	
Scheme/Programme: MAINTENANCE	old Maint.
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No } NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No }
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U } NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	U

Samir Kumar
(Signature) 16/12/20

NAME: SAMIR KUMAR

DESIGNATION: E-E

FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District: Samashpur	
Division : Samashpur		Length (km): 3.0km (East to West)	
Name of the Road: PWD Malpura Chowk to Dadpur Achey via Bhairavdehra Imli Chowk Simha Khand Panchayat			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance ☒	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ☒	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

Samiksha
(Signature) 16/12/20

NAME: SAMIR KUMAR

DESIGNATION: F.E

FIELD INSPECTION REPORT

Date of Inspection :	16/12/20	District:	Samalpur
Division :	Samalpur	Length (km):	1.20
Name of the Road:	D.D. J. L. Middle School & N.H. Bhangpur road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	old road
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓ NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No N/D
4.	Compliance History	
a)	Status of ATR's & any others	N/D

Overall Rating :

Satisfactory (S)	7
Satisfactory but requires Improvement (SRI)	7
Unsatisfactory (U)	0

Samalpur
(Signature) 16/12/2020

NAME: SAMIR KAMRAN

DESIGNATION: F.E

FIELD INSPECTION REPORT

Date of Inspection :	16/12/2022
Division :	Samastipur
Name of the Road :	Samastipur to Vikrampur Boudic chara
Scheme Programme :	MAINTENANCE
Package No. :	
Status of the Project :	Ongoing / Completed / Under Maintenance / New Connectivity / Upgradation / Maintenance
Road Id No. :	
Length (km) :	5.67
District :	Samastipur
Remarks :	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
1)	Road Junction condition	SU ✓
2)	Condition of Surfacing	SU ✓
3)	Finishing Quality	SU ✓
4)	Road Camber	SU ✓
5)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
6)	Contraction joints provided or not (CC Pavement)	Yes/No
7)	Compaction of Bank/slope & raincuts if any	Yes/No
8.	Cross Drainage	
1)	Condition of head walls in storm pipe culverts including the painting	SU ✓
2)	Condition of Abutment & Wing walls, Slab in RCC culverts	SU ✓
3)	Condition of railing/slab/approach for Bridges	SU ✓
4)	Good Drainage	
5)	Whether sign boards/informative board/kin & 20km	Yes/No
6)	Drainage/road markings are provided and maintained	Yes/No
7)	Condition of A.P.R. & any others	NA

Overall Rating	5
Satisfactory (S)	
Satisfactory but requires improvement (SI)	
Unsatisfactory (U)	

Carpet Area (sq.meters) 16/12/2022

Samastipur to Vikrampur Boudic chara

FIELD INSPECTION REPORT

Date of Inspection :	16/12/2021	District:	Samalpur
Division :	Samalpur	Length (km):	5.15
Name of the Road:	Jharkhand Sahitya Akademi Road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

Samir Kumar
(Signature) 16/12/2021

NAME: SAMIR KUMAR

DESIGNATION: E.E