

(11)

New M/R

FIELD INSPECTION REPORT

Date of Inspection:	16/12/2020	District:	Chhapra
Division:	Arn	Length (km):	0.64 KM
Name of the Road:	Bithaur-Nawada		
Scheme/Programme:	MAINTENANCE		
Package No.:	Am/BH/Am/12/0009	Road Id No.:	1040602025
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road's under	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	(N/A) Yes/No
f)	Contraction Joints provided or not (CC Pavement)	(N/A) Yes/No
g)	Composition of flank/slope & ruts/cuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/1m & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(S)

(Signature)

16/12/20

(N.A. ISHRAT)

NAME: