

(12) Old M/R

FIELD INSPECTION REPORT

Date of Inspection :	16/12/2020	District:	Bhojpur
Division :	Area	Length (km):	10.750 K.m
Name of the Road:	N.H. 84 Bibiganj to Saraniwar R.C.D. Road via Chitkundi, Kudiy, Belaghat, Shobha		
Scheme/Programme:	MAINTENANCE		
Package No.:	4091	Road Id No.:	10401608146
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U ✓	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, aggregates in case of CC Pavement.	exposed ✓ Yes/No Exposed aggregate	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & minecuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	Nil	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Remarks: Edge breakage at 2 places. Paintings on parapets not done properly.

NAME:

Rectification done : No
Rectification started : NO
Notice issued : No

(Signature) EE

(N.A. ISHRAT)