

old M/R

(9)

FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020	District: Bhojpur
Division : Arq	Length (km): 6.00 K.M.
Name of the Road: N.H. 84 Bibiganj to Ara Salampur R.C.D. Road via Ganghar Bahuapathari	
Scheme/Programme: MAINTENANCE	
Package No.: 10401608150	Road Id No.: 10401608150
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (needs to be rectified) ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & rineuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/1m & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Remarks: Faded edge marking. Sign board, informatory, cautionary boards not found. Road is polless but 200m surface needs rectification in some stretches.

Rectification done: No
 Rectification started: NO
 Notice issued: NO

NAME:

(Signature) 16/12/20

E.E.
 (N.A. ISHRAT)