

(10) Old M/R

FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020	District: Bhojpur	
Division : Ara	Length (km): 3.760 K.m.	
Name of the Road: Ara Buxar Road (N.H. 84) to Masrah Karisath Railway Station.		
Scheme/Programme:	MAINTENANCE	
Package No.: 5292	Road Id No.: 10401608160	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ☒
b)	Condition of Surfacing	S/U ☒
c)	Riding Quality	S/U ☒
d)	Road Camber	S/U ☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (needs rectifi.)
f)	Contraction Joints provided or not (CC Pavement)	(Yes/No) No cracks
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U }
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Remarks : Appearance of edge-breakage 2 pnts. (at 4 places) (at one place)

Rectification done : NO

Rectification started : NO

Notice issued : NO

NAME:

(Signature)

E.E.

(N.A. ISHRAT)