

# FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020	District: Gaya
Division : R.W.D. Work Division Gaya	Length (km): 2 km
Name of the Road: Gaya Phalehaur Road to Barela	
Scheme/Programme:	MAINTENANCE NEW.
Package No.: HR-N/19-20/Gaya 07	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No Raincuts
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

15/12/2020  
(Signature)

NAME: Sri Kant Prasad  
E.E.  
Regional Lab Saharua  
R.W.D.