

FIELD INSPECTION REPORT

15/12/20
AE

Date of Inspection : <i>15.12.20</i>	District: <i>Aurangabad</i>
Division : <i>Aurangabad</i>	Length (km): <i>18.90 km</i>
Name of the Road: <i>MR to Road from Balugan Vics Samola</i>	
Scheme/Programme: <i>MAINTENANCE</i>	<i>Sumari Road</i>
Package No.:	Road Id No.: <i>Head-3054 MR</i>
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<i>✓</i> S/U
b)	Condition of Surfacing	<i>✓</i> S/U
c)	Riding Quality	<i>✓</i> S/U
d)	Road Camber	<i>✓</i> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<i>✓</i> Yes/No
f)	Contraction Joints provided or not (CC Pavement)	<i>✓</i> Yes/No
g)	Compaction of flank/slope & raincuts if any	<i>✓</i> Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<i>✓</i> S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<i>✓</i> S/SRI/U
c)	Condition of railings/slab/approach for Bridges	<i>NA</i> S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	<i>✓</i> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	<i>—</i>

Overall Rating :

Satisfactory (S)	<i>—</i>
Satisfactory but requires Improvement (SRI)	<i>—</i>
Unsatisfactory (U)	<i>U</i>

NAME:

(Signature)

16/12/20
E.E
R Lab, Gubarg
Patel