

⑧ New M/R status: Ongoing

FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020	District: Bhojpur
Division : AY	Length (km): 2.03 K.M.
Name of the Road: Aya Baksee Path - Kaurik Dularpur Path	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BH/AYA/19/0003	Road Id No.: NEA22000707
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/1m & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

As the road is incomplete, following these entries is not possible at present

Overall Rating :

✓ N.A.

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Status: Ongoing. Only Pots have been filled in. SDBC & finishing work yet to be done.

(Signature)

EE & M3
(N.A. ISHRAT)

NAME: