

Sch. XLV- Form No. 134

| Particulars | Details of actual measurement |    |    |    | Contents or area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

ABSTRACT OF COST

2ND YEAR ON A/C BILL

(1)

found &amp; fix Bench

1

Mark Pillar on L

FMS

vp-2/4

Qty - 3 no

@ Rs 1768.55/m

5305 =

(2)

clong &amp; Crubing

2

the road land on

vp-2/5

Qty - 0.4526 Hs

@ Rs

51133 = 76/Ha. 24677 =

(3)

Dismissing the existing

3

Structure

FMS

vp-2/3

Qty - 49.50 H

@ Rs

231 = 771/m<sup>3</sup> 11472 =

(4)

Dismissing to cement

4

Cement are on

vp-1/2

Qty - 5.9614

@ Rs

406.831/m<sup>3</sup> 2425 =

(5)

Cost of embank

6

with approx soil

vp-5/5

level up to 100m

Executive Engineer  
R.W.D. Works Division  
BANKA-1



material statement

① Stanchion -  $84.48 \text{ m}^3$   
② 528.14 /  $\text{m}^3$

② Scaff -  $43.74 \text{ m}^3$   
③ 150.80 /  $\text{m}^3$

✓  $\text{cm}^3$   
8 / 12 / 2202  
21

Executive Engineer  
R.W.D. Works Division  
BANKA-1