

FIELD INSPECTION REPORT

Date of Inspection :	16/12/20	District:	PATNA
Division :	BARH	Length (km):	0.140
Name of the Road:	NH 30 A to Bhuaqur (Manghauli) PMGSY Road via Barh		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing ☒ Completed ☐ Under Maintenance ☐		
Work is a case of:	New Connectivity ☒ Upgradation ☐ Maintenance ☐ MMGSY (SC)		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S1
b)	Condition of Surfacing	✓ S1
c)	Riding Quality	✓ S1
d)	Road Camber	✓ S1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI 1
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S SRI 1
c)	Condition of railings slab/approach for Bridges	S SRI 1
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

—
—
"U"

Signature
16/12/20
(Signature)

NAME: BINOD KUMAR
JUNIOR ENGINEER