

FIELD INSPECTION REPORT

Date of Inspection :	14/12/20	District:	PATNA
Division :	BARH	Length (km):	0.550
Name of the Road:	Pragna Smayyash PMWSY Road to Malpur Bigha East Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing ☒ Completed ☐ Under Maintenance ☐		
Work is a case of:	New ☒ Collection ☐ Upgradation ☐ Maintenance ☐ MPMWSY(SC)		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road function condition	✓	
b)	Condition of Surfacing	✓	
c)	Riding Quality	✓	
d)	Road Camber	✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	No NA.	
f)	Construction joints provided or not (CC Pavement)	No NA.	
g)	Compaction of flank slope & cutouts if any	✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI	
b)	Condition of Abutments & Wing walls in RCC culverts	S SRI	
c)	Condition of roadings slab approach for Bridges	S SRI	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"SRI"

B. Kumar
14/12/20
(Signature)

NAME: BINOD KUMAR
JUNIOR ENGINEER