

Contractor:- Khushbu Kumari

U

FIELD INSPECTION REPORT

Date of Inspection: 14-12-2020	District: BANKA
Division: BANKA-2	Length (km): 0.668
Name of the Road: Rajawar Nawada Road To Laskari (BR03R386)	
Scheme/Programme: MAINTENANCE, 4th year	PMGSY
Package No.:	Road Id No.: 20703602185
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Ajay
14-12-2020
(Signature)

NAME: AJAY KUMAR

DESIGNATION: AS