

# FIELD INSPECTION REPORT

Date of Inspection : 12/12/20  
 Division : Banka-2 District : Banka  
 Name of the Road : Purniya Bhangya Path chandachh to chandachh  
 Scheme/Programme : MAINTENANCE Length (km): 4 In Yew.  
 Package No.: ROAD ID No.: 20703612038  
 Status of the Project: Ongoing/Completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

M.H. G.S.Y  
G.E.H

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | <b>Pavement</b>                                                                                                      |         |
| a)      | Road Junction condition                                                                                              |         |
| b)      | Condition of Surfacing                                                                                               | S/U     |
| c)      | Riding Quality                                                                                                       | S/U     |
| d)      | Road Camber                                                                                                          | S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | S/U     |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No  |
| 2.      | <b>Gross Drainage</b>                                                                                                | Yes/No  |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SR/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SR/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SR/U  |
| 3.      | <b>Road Furniture</b>                                                                                                |         |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |         |
| a)      | Status of ATR's & any others                                                                                         |         |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRU) | S |
| Unsatisfactory (U)                          |   |

NAME: Saijany Kumar  
 DESIGNATION: JE

12/12/20  
 (Signature)