

FIELD INSPECTION REPORT

Date of Inspection : 12/12/20
 Division : Banka-2 District: Banka
 Name of the Road: Poraichak to Ganghi Length (km): 1.526 KM
 Scheme/Programme: MAINTENANCE 4th Year.
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance Road Id No.: 20703613014
 Work is a case of: New Connectivity/Up gradation/ Maintenance

M.M.G.S.Y
(S.C.)

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


12/12/20
(Signature)

NAME: Saijay Kumar
 DESIGNATION: JR