

UTSNY.

FIELD INSPECTION REPORT

Date of Inspection :	16/12/20	District:	PATNA
Division :	BARH	Length (km):	0.520
Name of the Road:	Hasonchak to Sikandra road Harauli Chauhan Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	☒ New Connectivity ☐ Up gradation ☐ Maintenance UTSNY		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓	
b)	Condition of Surfacing	✓	
c)	Riding Quality	✓	
d)	Road Camber	✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓	
f)	Contraction Joints provided or not (CC Pavement)	✓	
g)	Compaction of flank slope & raneuis if any	✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its pointing	S SRII	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRII	
c)	Condition of railings slab approach for Bridges	S SRII	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

B Kumar
16/12/20
(Signature)

NAME: BINOD KUMAR
JUNIOR ENGINEER