## FIELD INSPECTION REPORT

	Inspection: \ (	1124 2020	District: Khagaria.	
Division		<del>Tegri</del>	Length (km): 1.207 KM.	
Scheme	Programme:	MAINTENANCE	Bunds to Mahadall	761a
Package		and Approved to a section of the sec	Road Id No.:	and the second second second second second
		Ongoing/Completed/	/Under Maintenance	
Work is	a case of:	New Connectivity/Up	gradation/ Maintenance	
SI. No.		Parameters to b	e checked	Remarks
1,	Pavement	Anna de la companya		legali da Ti
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			<b>√8/</b> U
c)	Riding Quality			<b>\%</b> /U
d)	Road Camber			√s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	ge ja		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance H	istory		
a)	Status of ATR'	s & any others	THE STATE OF THE S	

Satisfactory (S)	<i>-</i>	
Satisfactory but requires Improvement (SRI)	192	
Unsatisfactory (U)	-	

NAME:

DESIGNATION: