


FIELD INSPECTION REPORT

Date of Inspection : 12-12-20	District: Madhepura
Division: Uda Kishan Choudhary	Length (km): 1.425 km
Name of the Road: Mahadalit tola to Tatwa tola	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: - 1592814
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U / SRI
b)	Condition of Surfacing	S/U / SRI
c)	Riding Quality	S/U / SRI
d)	Road Camber	S/U / SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No / SRI
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/D

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 13/12/20
 J.B. Bhatnagar
 (Signature)