

MMGSY (Work Bank) Under 5 yrs maintenance

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020	District: Supaul.
Division : Vistpur	Length (km): 7.176
Name of the Road: Jaisam Chaudhary Buzar to Jaykajara Sukhahar Uq	
Scheme/Programme: M.S. Ram Tola - Sardar Tola.	
Package No.: —	Road Id No.: —
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	Not.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

[Signature]
16/12/20
(Signature)

NAME: Shri Nandan Pat. Guman
DESIGNATION: A.E. (Patap Ganj)