

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District : Purnea
Division : Purnea		Length (Km) : 3.819 Km
Name of the Road : 707 to chhatish chalis Bikrampatti.		
Scheme/Programme :	Maintenance ✓	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance ✓	
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No ✓
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
4).	Compliance History	
a)	Status of ATR's & any others	✓

Overall Rating :	Satisfactory (S)	✓
	Satisfactory but requires Improvement (SRI)	SRI ✓
	Unsatisfactory (U)	✓

Name : Gajendra Prasad Himantri
 Designation : J. E
 RWD, Works Division, Purnea.

Gajendra
 17.12.20
 (Signature)