

BAN MANIKHI

FIELD INSPECTION REPORT

Date of Inspection :	17/12/20	District:	PURNEA
Division :	R. W. D. Purne	Length (km):	2.750 km
Name of the Road:	Sargi - Bahigari SH to Kursela Natar via. M. Vidhyalaya budhiya		
Scheme/Programme:	MAINTENANCE	MA GST (CC)	
Package No.:	—	Road Id No.:	✓
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Main Sign boards provided ✓ Yes/No
4.	Compliance History	—
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	U
Unsatisfactory (U)	U

[Signature]
17/12/20
(Signature)

NAME: PANCHANAN MUNSHI
DESIGNATION: A.E., Banmankhi