


## FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District : Purnea
Division : Purnea		Length (Km) : 5.415 Km
Name of the Road : RD 87 To Paliga Ghat.		
Scheme/Programme :	Maintenance <input checked="" type="checkbox"/>	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of :	New Connectivity/Up gradation/Maintenance <input checked="" type="checkbox"/>	
Sl. No	Parameters to be Checked	Remarks
<b>1).</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <input checked="" type="checkbox"/>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <input checked="" type="checkbox"/>
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No <input checked="" type="checkbox"/>
<b>2).</b>	<b>Cross Drainage</b>	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U
<b>3).</b>	<b>Road Furniture</b>	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No <input checked="" type="checkbox"/>
<b>4).</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Name : Gajendra Prasad Himansu.  
 Designation : J.E  
 RWD, Works Division, Purnea.

  
 (Signature)  
 16/12/2020