

# FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District: purnea
Division : Baisi		Length (km): 2.680 km
Name of the Road: Khariya chowk to Ansari tola		
Scheme/Programme:	MAINTENANCE (MMGSY)	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	- U -
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

\* Mostly the road part of road damaged from flood; mostly flank/slope and raincut damaged due to flood.

Caum Kumar  
16/12/20  
(Signature)

NAME: GIJRAV KUMAR

DESIGNATION: ASSISTANT ENGINEER