FIELD INSPECTION REPORT

		1			
Date of Inspection: 16 12 2020			District : Katihar	District : Katihar	
Division: Katihar Name of the Road: Nawada to Baghawa Kol			Length (Km): 2.05.3		
Name of	the Road:	hwada to Bagh	awa Kol Under M	'M687-6,€N	
Scheme/Programme : Maintenance					
Package	No. :		Road ID No. : 21105512		
Status of the Project : Ongoing/Completed/Under Maintenance			Maintenance	1034	
Work is a case of:		New Connectivity/Up gradation/Maintenance			
Sl. No		Parameters to be C			
1).	Pavement	- additioners to be C	necked	Remarks	
a)	Road Junction condition				
b)	Condition of Surfacing			~S/U 5	
c)	Riding Quality			. S/U _S	
d)	Road Camber			∽S/U ,≲	
-				-s/u 5	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			V 0:	
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No S	
2).	Cross Drainage			.Yes/No S	
a)	Condition of Head walls in Hume Pipe Culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			s/sri/u S	
c)	Condition of Railings/Slab/Approach for Bridges			\$/SRI/U S	
3).	Road Furniture			√S/SRI/U S	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m				
4)	stones r avenient road markings are provided and maintained			Yes/No S	
4). a)	Compliance History				
a) Status of ATR's & any others				N.A.	
Owner H.B. of					
		Satisfactory (S)		5	
Satisfactory but requires Improvement (SRI)					
		Unsatisfactory (U)			
		Status:			

Name: Chandrahus Kumar

Degisnation: E.E.

RWD, Works Division, Katihar

(Signature) 16 121 200