FIELD INSPECTION REPORT

Date o	f Inspection: 16.	12.020	Dis	trict: KishamsenJ	
	n: Kishams			igth(km): 3.998 km	
		28 to Bish	nam	prix.	
Schem	e/Programme:	PMGSY			
Packag	e No.:	_		Road Id No.: 21205802073	
Status	of the Project:	Ongoing/Compl		/Under Maintenance	
Work is	a case of:	New Connectivity	ty/ U	p gradation / Maintenance	
S1. No		Parameters			Remarks
1.	Pavement				YS/U
a)	Road Junction Condition			~5/U	
b)	Condition of Surfacing				-5/U
c)	Riding Quality				~\$/U
d)	Road Camber				~\$/U
e)	Whether free fr	rom defects such	as vi	sible cracks, exposed aggregates	Yes/No
	in case of CC Pa	vement.		2	
f)	Contraction Join	nts Provided or no	ot (C	CC Pavement)	Yes/No
g)	Compaction of flank / shop & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of he	ad walls in Hume	pipe	culverts including its Painting	√S/SRI/U
b)	Condition of Ab	utment & Wing w	valls,	slab in RCC culverts	S/SRI/U
c)				S/SRI/U	
3.	Road Furniture				
a)	Whether sign bo	oards/informator	y/cai	utionary Board/km & 200m	Yes/No
	stones/Paveme	nt road markings	are p	provided and maintained	
4.	Compliance His				
a)	Status of ATR's	& any others			

Overall Rating:

Satisfactory(S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: RAKESH KUMAR.