| Date of Inspection: 17-12-2020 | | | District: Asosia | |
|--|--|--------------------|--------------------------|--------------|
| Name of the Road: Primay Aclos Scheme/Programme: MAINTENANCE | | | Length (km): | |
| Sakami | of the Road: | primay och | of paulusi to primar | schoolan |
| | | MAINTENANCE | V ' | July July |
| Package No.: Status of the Project: Ongoing/Completed | | | Road Id No.: | |
| Samp Compt. | | Ongoing/Completed | ed/Under Maintenance | |
| St. No. | | | p gradation/ Maintenance | |
| | | Parameters to | be checked | Remarks |
| 01.00 | Pavement | | | |
| a) | Road Junction | condition | | |
| b) | Condition of Surfacing | | | √8/U |
| e) | | | | √ 5/U |
| | Riding Quality | | | V87U |
| d) | Road Camber | | | . 8/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/Na |
| 1) | Contraction Joints provided or not (CC Pavement) | | | W no / |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. | Cross Drainage | | | 1 CS/15/4 |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | e/epr/ri |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | | ير S/SRI/U |
| 3. | Road Furniture | | | S/SRI/U M |
| | | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | YesiNo |
| | Compliance History | | | |
| a) : | Status of ATR's & any others | | | |
| | | | • | |
| Satisfactory (S) Satisfactory but requires Improvement (SRI | | | | |
| | | | uires Impanante de cons | 2 |
| | | Unsatisfactory (U) | an es improvement (SRI) | |

NAME: 77-12-2020
17.12.2020
A.E.

(Jisener Lis. Mandal

Rangeet Kr Mandal

(Signature)