


FIELD INSPECTION REPORT

Date of Inspection : 13/12/2020		District: Nalanda	
Division : Anwarsharif		Length (km): 1.00 km	
Name of the Road: 54-78 to Hetthanda Pul ke nikt se PMGSY Path Jak.			
Scheme/Programme: MAINTENANCE		MNP(4515)	
Package No.:		Road Id No.:	
Status of the Project: Ongoing /Completed/Under Maintenance			
Work is a case of: New Connectivity/Up-gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: Mojib Ahmad

DESIGNATION: J.E.