

FIELD INSPECTION REPORT

Date of Inspection :	16.12.2020	District: MUZAFFARPUR
Division :	EAST-1	Length (km):
Name of the Road:	NOTA MALIK KE GHAR SE INALI CHAWK HO TE HUE TO NUNAR TOLA JAGDISH DASWAN KE GHAR TAK	
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No.: 31507213 025
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Damaged during flood 2020 & water logging after ward.

Ashutosh Kumar
16.12.2020

(Signature)

NAME:

ASHUTOSH KUMAR

DESIGNATION:

JE-SAR