FIELD INSPECTION REPORT

Data of I	nspection: 7	112/2018	District: Huzaffas pur		
		Langer Gu	Builtenni: Lance		
Name of	the Road: Pa:	771111	Pur Awal TO Dil Tola		
	Programme:	MAINTENANCE			
Package	The state of the s		Road Id No.:		
	the Project:	Ongoing/Completed	Onder Maintenance		
	a case of:		p gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition			₩S/U	
b)	Condition of Surfacing			∟S/U	
c)	Riding Quality			_S/U	
d)	Road Camber			<u>-\$</u> /U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
n	Contraction Joints provided or not (CC Pavement)			Yes/No-	
g)	Compaction of flank/slope & raincuts if any			Yes/No.	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			VS/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N	
c)	Condition of railings/slab/approach for Bridges S/SRIA			S/SKI/U N	
3.	Road Furniture				
a)	Whether sign stones/Paveme	Yes/No			
4.	Compliance I	History			
a)		's & any others			

Overall Rating

Satisfactory (S)	. s
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

12/12/20

(Signature)

Sheo. Nafa Kanj

NAME:

DESIGNATION: