

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District: Muzaffarpur
Division : Muz - East - 2		Length (km): 1.500
Name of the Road: Rajkib Prathmin Vidyalay to Darigapur PWD Pass tar		
Scheme/Programme: MAINTENANCE M.M.L.S. (Green)		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

should be required maintenance

Information board required to be painted

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

At ch 1200, 1100 and many places surface is damaged. It requires to be maintain, shoulder, road furniture requires to be maintain, culvert required to painted

(Signature)

17.12.2020

NAME: Kamte P. S. Singh

DESIGNATION: J.E. Mirzapur