FIELD INSPECTION REPORT

Date of	Inspection: - C	3-12-2020	District: Muzofferpur		
Mysaffartus cast or			Length (km): 4.250 leng		
Name o	the Road: E		Middle Cehool Thojha		
	Programme:	MAINTENANCE			
Package			Road Id No.:		
			d/Under Maintenance		
	a case of:	New Connectivity/U	Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			,S/U	
c)	Riding Quality			U/S/U	
d)	Road Camber			SIU	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	ige			
a).	Condition of head walls in Hume pipe culverts including its painting			g S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N	
c)	Condition of railings/slab/approach for Bridges S/S			S/SRI/U N	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.				
4.	Compliance History				
a)	Status of ATR	t's & any others			

Overall Rating

Satisfactory (S)	"S "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Bandyaneth chandlery
DESIGNATION: J-E, Marhagenz