## FIELD INSPECTION REPORT

			District: MuzaHarpur	
	-		ength (km): 1.0 k·m	
	the Road: So	Lymarayan S	ah chowk to mill	a Chowle
	rogramme:	MAINTENÂNCE	(mmGsy)	
Package		Ongoing/Completed/U		
	the Project:		gradation/ Maintenance	
Work is a case of: Sl. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			_S/U
b)	Condition of Surfacing			LS/IU
c)	Riding Quality			₩.
d)	Road Camber			SIL
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S			S/SRI/U
<b>þ</b> )	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	•	
Satisfactory but requires Improvement (SRI)	"SPI"	
Unsatisfactory (U)		

NAME: Sanfosh Komar Pankaj DESIGNATION: Junior Engineer

Satosh v Panjenj.
(Signature) 05/12/2020
T.E
(BoChaha)

Scanned with CamScanner