FIELD INSPECTION REPORT					
Date of	Inspection:				
Division: All all District: Myzalfar hur					
Scheme/Programme: MAINTENANCE MMG13 Passite					ke Char to Paki
Package	the state of the s	Road	I Id No.:	31 28 15	e Chartale.
Status of the Project: Ongoing/Completed/Under Maintenance					1
Work is a case of: New Connectivity/Up gradation/ Maintenance				1	
Sl. No.	No. Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S ∕U	
b)	Condition of Surfacing			S(I)	1
c)	Riding Quality			✓ U	
d)	Road Camber			SU	j o
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			100	1
f)	Contraction Joints provided or not (CC Pavement)			Ves 30	1
g)	Compaction of flank/slope & raincuts if any			Yes/N	1
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			ting SRIT	
b)	Condition of Abutment & Wing walls, Slab in RCC eulverts			SRIT!	110
c)	Condition of railings/slab/approach for Bridges			XXXIII	7/4
3.	Road Furniture				
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained			00m Ses No	
4.	Compliance History			NO	1
a)	Status of ATR's & any others				
Overall I	Rating :	Satisfactory (S) Satisfactory but require Unsatisfactory (U)	s Improvement (SRI		
			4	(Signature)	
				Cargana	

NAME:

DESIGNATION: