FIELD INSPECTION REPORT

Divi		6-12-2020 District	· Maga than bev	_	,
	sion: Muz -	Fant - 9 Length	(km): 1.50 km	1	
Nam	ne of the Road: G	andhi Nagar	to machue t	oli .	
Sene	mc/rogramme:	MAINTENANCE			
	Package No.: Road Id No.: Status of the Project: Ongoing/Completed/Under Maintenance				
	k is a case of:	New Connectivity/Up gradation/ Maintenance			
SI. N	1			Remarks	
1.	Pavement			Achtavia	
a)	Road Junction	condition		S/U	`\$'
ь)	Condition of Surfacing		S/U _	U	
c)	Riding Quality			S/U	U
d)	Road Camber		S/U	5.	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
ŋ	Contraction Join	ts provided or not (CC Paverr	Yes/No	*	
g)	Compaction of flank/slope & raincuts if any Raincuts not			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	5 .
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	No provision
c)	Condition of railings/slab/approach for Bridges S/			S/SRI/U	No provisión
3.	Road Furniture				
	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained				sut not
4.	Compliance Hist	ory			
a) S	Status of ATR's & any others			No ATR	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

06.12.202

(Signature)

NAME: Ramte Pd. Sings

DESIGNATION: DE minapu

Scanned with CamScanner